

**PRE-FLOOD RIVER EMBANKMENT STATUS INSPECTION REPORT FOR THE YEAR 2019-20**

**SUNDARGARH IRRIGATION DIVISION, SUNDARGARH**

NAME OF THE SUB-DIVISION :- SUNDARGARH IRRIGATION SUB-DIVISION, SUNDARGARH

Sl. No.	Name of the Embankment	Category of the Embankment				Length in Km.	Name of the Basin	Name of the River	District	Reach	Status of the Embankment (Reach wise)						Brief Description about deficiency in parameters
		C.E.	O.A.E.	T.R.E.	S.E.						TBL "m"	Side Slope	Top Width "m"	Revertment "m" with location	Spur in nos. with location	17	
1	FPE on right bank of river Ichha near village Suruguda RD 00 to 345 Mtr. Lat- 22.1052/Long. 83.8431	3	4	5	6	0.345	Mahanadi	Ichha	Sundargarh	11	12	13	14	15	16	17	No deficiency detected till date
2	FPE on right bank of river Ichha near Tahasil Office of Lephrigara. RD. 00 to 300 Mtr. Lat- 22.1180/Long. 83.8056			T.R.E.		0.300	Mahanadi	Ichha	Sundargarh		253.700	1.5:1	1.50				No deficiency detected till date
3	FPE on right bank of river Ichha near village Chhatenpali RD 00 to 176 Mtr. Lat- 22.0938/Long. 83.8803			T.R.E.		0.176	Mahanadi	Ichha	Sundargarh		232.800	1.5:1	2.80	46.00			No deficiency detected till date
4	FPE on Left bank of river Ichha near village Jhartapali RD 00 to 120Mtr. Lat- 22.0832/Long. 83.8858			T.R.E.		0.120	Mahanadi	Ichha	Sundargarh		229.280	1.5:1	2.70				No deficiency detected till date

*Testified that inspected & verified 100% of embankment as listed above*

*B.M. 2.5.19*  
Assistant Engineer

*Inspected and verified 100% of embankment as listed above*

*Inspected and verified 100% of above embankment as listed above*

*Inspected and verified above embankment as listed above*

*Inspected and verified above embankment as listed above*

**COLLECTOR & DIST. MAGISTRATE  
SUNDARGARH**