

Embankment Inspection of Jonk Irrigation Division, Date.16.04.2021 & 17.04.2021 as per EE ,Jonk Irrigation Division Letter No.720(3)Dt.09.04.2021

Sl. No.	Basin	River	District	Block	Constituency	Left / Right	Name of the embankment	Observation	Length of Embankment in KM
1	2	3	4	5	6	7	8	9	10
1	Mahanadi	Jonk	Nuapada	Nuapada	Nuapada	L/R	Patora Embankment (Embankment near village Patora D/S of spillway)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.	0.80
2	Mahanadi	Kharkhara Nallah	Nuapada	Nuapada	Nuapada	R	Silda Embankment (Embankment near village Silda)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.	0.20
3	Mahanadi	Jonk	Nuapada	Nuapada	Nuapada	R	Kurumunda Embankment (Embankment over Jonk river near village Kurumunda)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.	0.90
4	Mahanadi	Kharkhara Nallah	Nuapada	Nuapada	Nuapada	L/R	Kalyanpur Embankment (Embankment near village Kalyanpur & U/S of Kharkhara barrage)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.	0.90
5	Mahanadi	Kharkhara Nallah	Nuapada	Nuapada	Nuapada	L	Chanabeda Embankment (Embankment near village Chanabeda in D/S of Kharkhara barrage)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.	0.60
6	Mahanadi	Kharkhara Nallah	Nuapada	Nuapada	Nuapada	L/R	Mahatamtora Embankment (Embankment near village Mahatamtora of Kharkhara nallah)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.	0.50

7	Mahanadi	Sundar	Nuapada	Komna	Nuapada	L/R	Ichhapur Embankment (Embankment near village Ichhapur in D/S of spillway of Sundar Irrigation Project)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.	2.00
8	Mahanadi	Arjun Jharia Nallah	Nuapada	Komna	Nuapada	L/R	Thongo Embankment (Embankment near village Thongo)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.	0.90
TOTAL									6.80

I have visited the river embankments from SI.No.1 & 3 covering 100% length and there is no vulnerable points noticed.

Asst. Engineer
16/4/21

I have visited the river embankments from SI.No.2,4,5 & 6 covering 100% length and there is no vulnerable points noticed.

Asst. Engineer
17/4/2021

I have visited the river embankments from SI.No.7 & 8 covering 100% length and there is no vulnerable points noticed.

Junior Engineer
17.04.21

Block Development Officer
Komna

Chairman,
panchayat Samit, Komna

O. Kaman
17/4/21
R. I. nichirapan

Block Development Officer
Nuapada
17.04.2021

Chairman
panchayat Samit, Nuapada

I have visited the river embankments from SI.No.1 to 3 covering 100% length and there is no vulnerable points noticed.

Sub-Divisional Officer
16/4/21

I have visited the river embankments from SI.No.2,4,5 to 6 covering 100% length and there is no vulnerable points noticed.

Sub-Divisional Officer
17.04.21

Sub-Divisional Officer
17.04.21

Executive Engineer
Jonk Irrigation Division,
Nuapada

Countersignature
COLLECTOR
NUAPADA