

STATUS OF IRRIGATION SUPPLIED DURING KHARIF AS ON SEPTEMBER 2015 IN ANGUL DISTRICT

Sl No.	Name of District	Name of Block	Name of MIP	Length of canal system in Km		Ayacut in Ha.			Reason for less/ excess of ayacut irrigated/ Reason for not reaching tail end
				Design length	Actual length in which water supplied	Designed Ayacut	Actual Potential Created	Ayacut irrigated upto 15th Sept'2015	
1	2	3	4	5	6	7	8	9	10
1	Angul	Angul	Bauli	17.37	15.45	1180.00	984.00	984.00	Branch canal No. 6,7,8 require repair of canal structures and resectioning of canal.
2	Angul	Angul	Bhimdarh	1.13	1.00	121.00	40.00	40.00	Due to less rain fall
3	Angul	Angul	Chanaghai	2.61	1.75	142.00	130.00	130.00	Due to less rain fall
4	Angul	Angul	Chhotokoi	1.85	1.88	62.00	57.00	57.00	Due to less rain fall
5	Angul	Angul	Gopalpur	2.43	2.43	194.00	189	189.00	Due to less rain fall
6	Angul	Angul	Guranga	3.95	3.95	182.00	184.00	184.00	Due to less rain fall
7	Angul	Angul	Jaganathpur	1.29	1.29	101.00	59.00	59.00	Due to less rain fall
8	Angul	Angul	Kanja	0.80	0.80	200.00	20.00	20.00	Only 800m D/S existing
9	Angul	Angul	Kothabhuin	1.25	1.25	41.00	41.00	41.00	Full ayacut achieve
10	Angul	Angul	Matellia	7.41	7.41	433.00	433.00	433.00	Full ayacut achieve
11	Angul	Angul	Sabalbhanga	1.70	1.50	105.00	105.00	105.00	Full ayacut achieve
12	Angul	Angul	Takua	9.64	8.95	377.00	496.00	496.00	Full ayacut achieve
13	Angul	Angul	Talapada	0.60	0.60	53.00	30.00	30.00	Full ayacut achieve
14	Angul	Angul	Garambandha	0.90	0.90	41.00	40.00	40.00	Full ayacut achieve
15	Angul	Angul	Deulabandha	0.70	0.40	121.00	50.00	50.00	Due to less rain fall
16	Angul	Athamallik	Aida	3.27	2.90	136.00	134.00	120.00	Due to less rain fall
17	Angul	Athamallik	Bileikhai	4.55	4.55	233.00	233.00	233.00	Full ayacut achieve
18	Angul	Athamallik	Dahimal	1.09	1.09	81.00	45.00	30.00	Due to less rain fall
19	Angul	Athamallik	Dhuliapada	0.85	0.85	61.00	49.00	40.00	Due to less rain fall
20	Angul	Athamallik	Gangapani	0.81	0.81	81.00	30.00	30.00	Due to less rain fall
21	Angul	Athamallik	Jhilimunda	3.44	3.44	162.00	162.00	150.00	Due to less rain fall
22	Angul	Athamallik	Jogibandha	1.10	1.10	162.00	67.00	60.00	Due to less rain fall
23	Angul	Athamallik	Kadapada	1.00	1.00	41.00	28.00	25.00	Due to less rain fall
24	Angul	Athamallik	Kalamati	0.74	0.74	61.00	61.00	61.00	Full ayacut achieve
25	Angul	Athamallik	Kaliadarh	4.99	1.60	81.00	68.00	40.00	Due to less rain fall
26	Angul	Athamallik	Ketakijhar	0.20	0.20	73.00	15.00	40.00	Renovation required.
27	Angul	Athamallik	Khajurijoda	2.43	2.43	81.00	81.00	35.00	Due to less rain fall
28	Angul	Athamallik	Kishoresagar	2.43	1.30	89.00	89.00	89.00	Full ayacut achieve
29	Angul	Athamallik	Laupal	7.49	6.90	324.00	413.00	324.00	Due to less rain fall
30	Angul	Athamallik	Lehed	1.96	1.10	162.00	104.00	80.00	Due to less rain fall
31	Angul	Athamallik	Lunahandi Sagar	3.25	3.25	162.00	149.00	140.00	Due to less rain fall
32	Angul	Athamallik	Mandarbahal	1.00	1.00	41.00	25.00	25.00	Field to field irrigation
33	Angul	Athamallik	Mangalpur	0.54	0.50	121.00	45.00	40.00	Less rainfall
34	Angul	Athamallik	Mankadkenda	3.12	1.50	81.00	81.00	40.00	Due to less rain fall
35	Angul	Athamallik	Patka-I		0.50	202.00	60.00	40.00	Due to less rain fall & damage in canal system.
36	Angul	Athamallik	Patrapada	1.50	1.00	41.00	25.00	25.00	NCS
37	Angul	Athamallik	Podapadar		0.10	41.00	26.00	25.00	NCS
38	Angul	Athamallik	Rajabandha	3.42	3.42	134.00	147.00	134.00	Full ayacut
39	Angul	Athamallik	Ranibandha	0.15	0.15	41.00	41.00	25.00	Due to less rain fall
40	Angul	Athamallik	Sankhamal	2.75	1.50	41.00	68.00	30.00	Due to less rain fall
41	Angul	Banarpal	Kuio-Integrate Scheme	2.20	2.20	142.00	162.00	162.00	Renovated through OCTMP scheme
42	Angul	Banarpal	Santrapur	2.40	2.00	41.00	30.00	30.00	Due to less rain fall & Siltation of canal.
43	Angul	Chhendipada	Balibandh Integrated Scheme	8.83	4.25	401.00	355.00	355.00	Due to less rain fall & damage in canal system.
44	Angul	Chhendipada	Chhendipada Jungle	0.50	0.50	101.00	60.00	42.00	Due to less rain fall
45	Angul	Chhendipada	Gouduninalla	1.83	1.20	81.00	60.00	50.00	Due to less rain fall
46	Angul	Chhendipada	Jamelijharan	1.10	0.50	81.00	84.00	84.00	Due to less rain fall & non maintenance of canal
47	Angul	Chhendipada	Jhintipal	1.39	1.39	162.00	90.00	90.00	Due to less rain fall
48	Angul	Chhendipada	Kansabansa	18.18	11.30	972.00	848.00	848.00	Due to less rain fall
49	Angul	Chhendipada	Kukurpetta	7.89	6.20	587.00	528.00	528.00	Due to less rain fall
50	Angul	Chhendipada	Kumbhira	4.83	3.83	267.00	285.00	285.00	Due to less rain fall
51	Angul	Chhendipada	Paranga	7.10	5.20	600.00	600.00	600.00	Due to less rain fall
52	Angul	Chhendipada	Patrapada	20.78	7.50	1526.00	911.00	911.00	Due to less rain fall & non maintenance of canal
53	Angul	Chhendipada	Raijharan	6.76	6.76	344.00	286.00	286.00	Due to less rain fall
54	Angul	Chhendipada	Katada			41.00	30.00	30.00	Irrigation provide through field to field
55	Angul	Kaniha	Balijodi	3.29	3.29	191.00	130.00	130.00	Due to less rain fall
56	Angul	Kaniha	Deojada	5.30	1.50	121.00	60.00	60.00	Due to less rain fall & canal required renovation
57	Angul	Kaniha	Kishore sagar	1.00	0.70	48.00	39.00	39.00	Due to less rain fall
58	Angul	Kaniha	Nuabandha(Kuluma)			41.00	32.00	32.00	Irrigation provide through field to field
59	Angul	Kaniha	Ghasiaposi	10.69	4.50	322.00	170.00	170.00	Due to less rain fall & non maintenance of canal
60	Angul	Kishorenagar	Ambapal	3.30	3.30	81.00	81.00	81.00	Full ayacut
61	Angul	Kishorenagar	Asrubahal	1.10	1.10	41.00	41.00	31.00	Scanty Rainfall

62	Angul	Kishorenagar	Dalimura	3.50	3.50	280.00	200.00	50.00	Renovation work of distribution system is in progress under 'OCTMP' scheme. On completion, water will reach at tail end.
63	Angul	Kishorenagar	Garuda	0.30	0.20	41.00	30.00	30.00	Due to less rain fall
64	Angul	Kishorenagar	Goratopa	3.20	2.50	109.00	100.00	50.00	Renovation of of canal system is required.
65	Angul	Kishorenagar	Jaigarh	19.90	13.50	729.00	530.00	530.00	Renovation of of canal system is required.
66	Angul	Kishorenagar	Padiabandhapali	0.10	0.10	80.00	50.00	40.00	Canal system not completed
67	Angul	Kishorenagar	Sargipali	2.16	2.16	118.00	134.00	134.00	Full ayacut
68	Angul	Kishorenagar	Sureswari (including Linking of 10 tanks)	18.54	11.20	785.00	510.00	510.00	Canal system not completed
69	Angul	Kishorenagar	Susab	6.50	6.00	249.00	249.00	249.00	Full ayacut
70	Angul	Kishorenagar	Thelkonali	5.80	5.80	243.00	243.00	181.00	Due to less rain fall and canal needs repair.
71	Angul	Pallahara	Andhari	8.75	8.75	445.00	561.00	561.00	Renovated through OCTMP Scheme
72	Angul	Pallahara	Aunli	3.38	2.50	110.00	60.00	60.00	Renovated through OCTMP Scheme
73	Angul	Pallahara	Dalo	2.64	2.64	132.00	143.00	143.00	Renovated through OCTMP Scheme
74	Angul	Pallahara	Gandijore	8.65	8.65	597.00	414.00	414.00	Renovated through OCTMP Scheme
75	Angul	Pallahara	Khuntapasi	3.48	2.20	162.00	75.00	75.00	Due to less rain fall
76	Angul	Pallahara	Mankada	37.45	37.45	2000.00	1935.00	1935.00	Less rainfall
77	Angul	Pallahara	Janara (Jamarkella)			121.00	40.00	30.00	On-going.
78	Angul	Pallahara	Saliamunda (Ghagara)	4.58	3.00	243.00	242.00	242.00	H/R, canal and falls damaged
79	Angul	Talcher	Bhalugadia	3.08	3.08	121.00	106.00	106.00	Ayacut area occupied by MCL
80	Angul	Talcher	Phulmukha	3.20	0.20	81.00	17.00	17.00	Canal requires renovation.
81	Angul	Talcher	Karnapur	0.33	0.33	60.00	25.00	25.00	Due to less rain fall
			Total:	349.68	273.43	18983.00	15461.00	14965.00	