

**STATUS OF IRRIGATION SUPPLIED DURING KHARIFF AS ON SEPTEMBER 2015 IN MAYURBHANJ DISTRICT**

Sl No.	Name of District	Name of Block	Name of MIP	Length of canal system (in Km)		Ayacut in Ha.			Reason for less/ excess of ayacut irrigated/ Reason for not reaching tail end
				Design length	Actual length in which water supplied	Designed Ayacut	Actual Potential Created	Ayacut irrigated upto 15th Sept'2015	
1	2	3	4	5	6	7	8	9	10
1	Mayurbhanj	Bangriposi	Dambasakhal	3.58	2.58	120.00	120.00	120.00	Full ayacut achieve
2	Mayurbhanj	Bangriposi	Dasisole MIP	4.2	3.2	100.00	80.00	80.00	less rain fall
3	Mayurbhanj	Bangriposi	Ghatkuanri MIP	1.5	1.5	30.00	40.00	30.00	less rain fall
4	Mayurbhanj	Bangriposi	Gohirapal			100.00	0.00		New project proposed under RIDF and deleted
5	Mayurbhanj	Bangriposi	Kasiabeda	1.2	1.2	80.00	70.00	70.00	less rain fall
6	Mayurbhanj	Bangriposi	Mahupahadi	2.5	2.5	120.00	120.00	120.00	Full ayacut achieve
7	Mayurbhanj	Bangriposi	Nedam	11.2	9.4	380.00	360.00	360.00	Due to less rain fall, less water in Reservoir
8	Mayurbhanj	Baripada	Badjore	26.76	25.5	1280.00	1200.00	1200.00	Ayacut of tail reach of Left Main canal & its BC No-4 are not getting adequate irrigation due to long canal system & as the canal runs in latrite bed. Proposed under CLSRP for better irrigation efficiency.
9	Mayurbhanj	Baripada	K.C Pur (I) MIP (Res)	1.8	1	40.00	40.00	30.00	Due to less rain fall, less water in Reservoir
10	Mayurbhanj	Baripada	K.C Pur (II) MIP (Res)	2.5	1	40.00	40.00	25.00	Due to less rain fall, less water in Reservoir
11	Mayurbhanj	Baripada	Kainfulia MIP (Res)	1.5	0.6	80.00	40.00	40.00	Due to conversion of agricultural land to home stead land as the MIP is located adjacent to Town.
12	Mayurbhanj	Baripada	Kathapal MIP (Res)	3.48	2.5	120.00	80.00	0.00	Present water level is below FRL
13	Mayurbhanj	Baripada	Munsibandha MIP (Res)	2	1	44.00	40.00	25.00	Due to conversion of agricultural land to home stead land as the MIP is located adjacent to Town.
14	Mayurbhanj	Baripada	Rajabasa MIP (Res)	3	2	80.00	80.00	60.00	Present water level is below FRL
15	Mayurbhanj	Baripada	Sandakoi MIP (Res)	3	2	52.00	52.00	40.00	Present water level is below FRL
16	Mayurbhanj	Barsahi	Astajharan	0.95	0.95	40.00	40.00	40.00	Full ayacut achieve
17	Mayurbhanj	Barsahi	Baiganbadia (D/W)	3.86	3.86	170.00	170.00	170.00	Full ayacut achieve
18	Mayurbhanj	Barsahi	Belam	1.2	1.2	60.00	60.00	60.00	Full ayacut achieve
19	Mayurbhanj	Barsahi	Chekamara	2.3	2.3	100.00	100.00	100.00	Full ayacut achieve
20	Mayurbhanj	Barsahi	Hinjalagadia	3.17	3.17	76.00	76.00	76.00	Full ayacut achieve
21	Mayurbhanj	Barsahi	Jodipal	1.44	1.44	120.00	120.00	120.00	Full ayacut achieve
22	Mayurbhanj	Barsahi	Kanimahuli	1.61	1.61	80.00	80.00	80.00	Full ayacut achieve
23	Mayurbhanj	Barsahi	Kauchibundha	0.67	0.67	40.00	40.00	40.00	Full ayacut achieve
24	Mayurbhanj	Barsahi	Madhabinalla	13.533	13.533	400.00	400.00	400.00	Full ayacut achieve
25	Mayurbhanj	Barsahi	Mantrikundi	0.5	0.5	80.00	80.00	80.00	Full ayacut achieve
26	Mayurbhanj	Barsahi	Manuadhupa	1	1	120.00	120.00	120.00	Full ayacut achieve
27	Mayurbhanj	Barsahi	Paunsianalla	14.22	14.22	600.00	600.00	600.00	Full ayacut achieve
28	Mayurbhanj	Barsahi	Purnachandrapur	2	2	60.00	60.00	60.00	Full ayacut achieve
29	Mayurbhanj	Barsahi	Purunapani	2.5	2.5	50.00	50.00	50.00	Full ayacut achieve
30	Mayurbhanj	Barsahi	Rajabundha	1	1	52.00	52.00	52.00	Full ayacut achieve
31	Mayurbhanj	Betnoti	Ambojoda	3.42	3.42	60.00	60.00	60.00	Full ayacut achieve
32	Mayurbhanj	Betnoti	Baghabasa (D/W)	2.48	2.48	412.00	412.00	412.00	Full ayacut achieve
33	Mayurbhanj	Betnoti	Baunsanadi	9.87	9.87	400.00	400.00	400.00	Full ayacut achieve
34	Mayurbhanj	Betnoti	Jamsole	1	1	40.00	40.00	40.00	Full ayacut achieve
35	Mayurbhanj	Betnoti	Saria	2.56	2.56	100.00	100.00	100.00	Full ayacut achieve
36	Mayurbhanj	Betnoti	Sukhilahar	1.2	1.2	40.00	40.00	40.00	Full ayacut achieve
37	Mayurbhanj	Bisoi	Badnalua	4.2	4.2	140.00	140.00	140.00	Full ayacut achieve
38	Mayurbhanj	Bisoi	Baghiatagar	3	3	40.00	40.00	40.00	Full ayacut achieve
39	Mayurbhanj	Bisoi	Bisoinala			40.00	0.00		Ayacut converted to homestead land
40	Mayurbhanj	Bisoi	Budhikhamari	2	2	260.00	260.00	260.00	Full ayacut achieve
41	Mayurbhanj	Bisoi	Jamirdiha	1.9	1.9	124.00	124.00	124.00	Full ayacut achieve
42	Mayurbhanj	Bisoi	Kasipani	7.71	7.71	223.00	223.00	223.00	Full ayacut achieve
43	Mayurbhanj	Bisoi	Kuliposi	1.82	1.82	76.00	76.00	76.00	Full ayacut achieve
44	Mayurbhanj	Bisoi	Radhanagar (D/W)	3	3	48.00	48.00	48.00	Full ayacut achieve
45	Mayurbhanj	Bisoi	Ruliabindha	1.5	1.5	50.00	50.00	50.00	Full ayacut achieve
46	Mayurbhanj	Bisoi	Srirampur	1	1	72.00	72.00	57.00	Due to less rain fall, less flow in Nalla
47	Mayurbhanj	G.B. Nagar	Astia (D/W)	1.62	0.72	121.00	40.00	40.00	Balance canal needs renovation.
48	Mayurbhanj	G.B. Nagar	Charada (Res)	1.02	1.02	81.00	81.00	81.00	Water reaching upto tail end
49	Mayurbhanj	G.B. Nagar	Chaturi MIP (Res)	1.75	0.75	60.00	30.00	30.00	R.M.C of 1 km to be constructed
50	Mayurbhanj	G.B. Nagar	Ghantasila (Res)	4.98	3.6	135.00	85.00	85.00	less rain fall
51	Mayurbhanj	G.B. Nagar	Gududiha MIP	0.45	0.4	40.00	40.00	30.00	less rain fall
52	Mayurbhanj	G.B. Nagar	Krushnasagar MIP	0.51	0.51	32.00	40.00	25.00	Due to less rain fall
53	Mayurbhanj	G.B. Nagar	Mahulia MIP (Res)	1.1	0.8	40.00	40.00	30.00	Due to less rain fall
54	Mayurbhanj	G.B. Nagar	Naharadesbundha (Res)	1.55	1.2	80.00	60.00	50.00	Present water level is below FRL
55	Mayurbhanj	G.B. Nagar	Padmapur MIP	0.45	0.45	40.00	40.00	35.00	Due to less rain fall
56	Mayurbhanj	G.B. Nagar	Pathurikati MIP (Res)	1.6	1	60.00	50.00	40.00	Present water level is below FRL

57	Mayurbhanj	G.B. Nagar	Raidihi (D/W)	0.6	0.5	60.00	40.00	20.00	Less run-off due to scanty rainfall.
58	Mayurbhanj	G.B. Nagar	Sanbelakuti (Res)	1.75	1.75	111.00	111.00	111.00	Full ayacut achieve
59	Mayurbhanj	G.B. Nagar	Silaghati (Res)	1.54	1.5	49.00	49.00	45.00	Present water level is below FRL
60	Mayurbhanj	Kaptipada	Ghantabilla			52.00	0.00	0.00	Over lapped by Sunei Irrigation Project
61	Mayurbhanj	Kaptipada	Jamsole			40.00	0.00	0.00	Over lapped by Sunei Irrigation Project
62	Mayurbhanj	Kaptipada	Katuria			100.00	0.00	0.00	Over lapped by Sunei Irrigation Project
63	Mayurbhanj	Kaptipada	Kespada (D/W)	3.05	2.1	127.00	60.00	52.00	Less run-off due to scanty rainfall
64	Mayurbhanj	Kaptipada	Mahabali (Res)	4	2.8	43.00	40.00	30.00	Present water level is below FRL
65	Mayurbhanj	Kaptipada	Majhigadia (Res)	2.2	2	48.00	48.00	47.00	Present water level is below FRL
66	Mayurbhanj	Kaptipada	Mundasahi (Res)	1.25	1.1	50.00	50.00	40.00	Present water level is below FRL
67	Mayurbhanj	Kaptipada	Purunapani (Res)	3	2.5	58.00	58.00	50.00	Present water level is below FRL
68	Mayurbhanj	Kaptipada	Rangamatia (Res)	1	1	40.00	40.00	30.00	Present water level is below FRL
69	Mayurbhanj	Kaptipada	Ranibundha	1	0	40.00	40.00	0.00	canal work in progress
70	Mayurbhanj	Kaptipada	Tumtumka-Katuribentia	2.89	0	100.00	60.00	0.00	canal work in progress
71	Mayurbhanj	Khunta	Arikul (Res)	15.65	12.5	1000.00	815.00	815.00	Work is in progress
72	Mayurbhanj	Khunta	Gangahar (D/W)	28.51	21.2	1920.00	1660.00	1660.00	Less run-off due to scanty rainfall
73	Mayurbhanj	Khunta	Gohiraduba (D/W)	7.26	5.3	460.00	425.00	400.00	Less availability of water in river
74	Mayurbhanj	Khunta	Haldipal	2.5	1.1	40.00	40.00	20.00	PR transferred Project, renovation is in progress.
75	Mayurbhanj	Khunta	Khandabuda (D/W)	6.5	5.4	40.00	60.00	35.00	Renovation work in progress
76	Mayurbhanj	Khunta	Nalua (D/W)	31.55	28.4	2006.00	2000.00	1900.00	Renovation work in progress
77	Mayurbhanj	Khunta	Olgadajhar (Res)	2.12	2.12	80.00	78.00	78.00	
78	Mayurbhanj	Khunta	Talkunda (D/W)	1.65	1.1	40.00	30.00	30.00	
79	Mayurbhanj	Khunta	Tulsabundha			56.00	0.00	0.00	Res. In pvtland
80	Mayurbhanj	Kuliana	Chaluniakhal MIP (D/W)	3.3	2	118.00	0.00	0.00	D/W damaged & work in progress
81	Mayurbhanj	Kuliana	Gyalkata MIP (Res)	3.85	3	162.00	110.00	110.00	Less rain fall
82	Mayurbhanj	Kuliana	Jagannathpur	1.68	1.2	75.00	75.00	60.00	Present water level is below FRL
83	Mayurbhanj	Kuliana	Jilidam			80.00	0.00		No.independent ayacut. Ayacut under other MIP.
84	Mayurbhanj	Kuliana	Katharuma MIP (Res)	1.5	1	60.00	45.00	45.00	Present water level is below FRL
85	Mayurbhanj	Kuliana	Sankarama (Res)	16.5	6	668.00	420.00	420.00	Present water level is below FRL & heavy seepage is observed in canal due to nature of soil. So canal lining is required.
86	Mayurbhanj	Morada	Anua	4.31	3.1	200.00	195.00	155.00	Due to less rain fall,less water in Reservoir,CD
87	Mayurbhanj	Morada	Baunsakhal	1.74	1.44	61.00	61.00	50.00	Due to less rain fall,less water in Reservoir
88	Mayurbhanj	Morada	Chhadakata	2.6	0.8	130.00	134.00	65.00	Due to less rain fall,less water in Reservoir
89	Mayurbhanj	Morada	Dantiamuhan	2.18	1.9	90.00	88.00	75.00	Due to less rain fall,less water in Reservoir,
90	Mayurbhanj	Morada	Futukisole	1.2	1	65.00	56.00	56.00	Ayacut comes under SIP command
91	Mayurbhanj	Morada	Ghagara	2.2	1.2	40.00	40.00	25.00	HW in private land,no HR & Surplus escape improvement not allowed by owner.
92	Mayurbhanj	Morada	Ghodabandha	3.81	3.2	40.00	41.00	35.00	Due to less rain fall,less water in Reservoir
93	Mayurbhanj	Morada	Godigaon	4.15	3.15	150.00	127.00	115.00	Part of Right canal in private land, improvement not allowed by owner.
94	Mayurbhanj	Morada	Jamugadia	2.71	0.7	40.00	40.00	15.00	Transferred during 2012 for improvement under RR&R.Private land involved,no HR,Surplus escape & defined canal system.
95	Mayurbhanj	Morada	Jhinkiria(D/W)	5.47	5	140.00	140.00	110.00	Due to less rain fall,less flow in Nalla.
96	Mayurbhanj	Morada	Kandana	2.13	1.8	45.00	45.00	35.00	Due to less rain fall,less water in Reservoir
97	Mayurbhanj	Morada	Khejuria	2	0.7	120.00	118.00	45.00	Due to less rain fall,less water in Reservoir
98	Mayurbhanj	Morada	Mahulabani	3.28	2.5	107.00	107.00	82.00	Due to less rain fall,less water in Reservoir
99	Mayurbhanj	Morada	Morada(D/W)	4.06	3.6	170.00	158.00	158.00	Due to less rain fall,less flow in Nalla
100	Mayurbhanj	Morada	Nadia	0.94	0.7	62.00	62.00	42.00	Due to less rain fall,less water in Reservoir
101	Mayurbhanj	Morada	Podakhunta(D/W)	1.2	0.9	40.00	40.00	32.00	Due to less rain fall,less flow in Nalla.Transferred during 2012 for improvement under RR&R.Private land involved in H/W no defined canal system.
102	Mayurbhanj	Morada	Purunapani	1.76	1.4	40.00	40.00	32.00	Due to less rain fall,less water in Reservoir

103	Mayurbhanj	Morada	Sirsapal	6.18	5.7	266.00	262.00	250.00	Due to less rain fall,less water in Reservoir
104	Mayurbhanj	Rasgvindapur	Amarda	0.82	0.82	60.00	60.00	60.00	Full ayacut achieve
105	Mayurbhanj	Rasgvindapur	Kandarasole	1.3	1.3	40.00	40.00	40.00	Full ayacut achieve
106	Mayurbhanj	Rasgvindapur	Kiakhal	2.5	2.5	120.00	120.00	120.00	Full ayacut achieve
107	Mayurbhanj	Rasgvindapur	Kuchiasole	1.13	1.13	40.00	42.00	40.00	Full ayacut achieve
108	Mayurbhanj	Rasgvindapur	Kulipal	2.5	2.5	60.00	60.00	60.00	Full ayacut achieve
109	Mayurbhanj	Rasgvindapur	Madhuria	1.22	1.22	40.00	40.00	40.00	Full ayacut achieve
110	Mayurbhanj	Rasgvindapur	Rasgovindapur	1.32	1.32	120.00	122.00	120.00	Full ayacut achieve
111	Mayurbhanj	Rasgvindapur	Sananai	10	0	680.00	0.00	0.00	Ayacut under SIP command
112	Mayurbhanj	Rasgvindapur	Ugalsandha	1.53	1.53	55.00	55.00	55.00	Full ayacut achieve
113	Mayurbhanj	Rasgvindapur	Ukasole	0.98	0.98	40.00	40.00	40.00	Full ayacut achieve
114	Mayurbhanj	Samakhunta	Alubani MIP (Res)	9.64	5	168.00	150.00	100.00	Present water level is below FRL
115	Mayurbhanj	Samakhunta	Ambadali MIP (D/W)	1.6	0	80.00	0.00	0.00	D/W damaged due to Phailin
116	Mayurbhanj	Samakhunta	Bahadarpur			60.00	0.00	0.00	D/W damaged due to Phailin.Pvt. Land involved
117	Mayurbhanj	Samakhunta	Baunsabilla MIP (D/W)	13.6	6	700.00	400.00	400.00	
118	Mayurbhanj	Samakhunta	Chandanpur MIP	2	1	80.00	50.00	40.00	Present water level is below FRL
119	Mayurbhanj	Samakhunta	Digdiga MIP (D/W)	2.6	2	100.00	55.00	45.00	Less run-off due to scanty rainfall.
120	Mayurbhanj	Samakhunta	Itabandha MIP(Res)	0.6	0.5	200.00	200.00	150.00	Present water level is below FRL
121	Mayurbhanj	Samakhunta	Jualirama MIP (D/W)	1	0	125.00	0.00	0.00	D/W damaged due to Phailin
122	Mayurbhanj	Samakhunta	Kendua MIP(Res)	3.9	2.9	150.00	100.00	75.00	Present water level is below FRL
123	Mayurbhanj	Samakhunta	Khandia MIP (D/W)	2.8	0	202.00	0.00	0.00	D/W damaged due to Phailin
124	Mayurbhanj	Saraskana	Astia	NSC	NSC	100.00	0.00	0.00	Over lapped by SIP
125	Mayurbhanj	Saraskana	Belbaria	1.95	1.95	74.00	74.00	74.00	Full ayacut achieve
126	Mayurbhanj	Saraskana	Bhursani	1.95	1.95	50.00	50.00	50.00	Full ayacut achieve
127	Mayurbhanj	Saraskana	Danadar	0.7	0.7	56.00	56.00	56.00	Full ayacut achieve
128	Mayurbhanj	Saraskana	Dumuria			130.00	0.00	0.00	Handed over to SIP
129	Mayurbhanj	Saraskana	Jambani	0.5	0.5	64.00	64.00	64.00	Full ayacut achieve
130	Mayurbhanj	Saraskana	Maharabundha	0.75	0.75	50.00	50.00	50.00	Full ayacut achieve
131	Mayurbhanj	Saraskana	Mahulbarai	NSC	NSC	56.00	0.00	0.00	Over lapped by SIP
132	Mayurbhanj	Saraskana	Pahadpur	4.7	4.7	64.00	64.00	64.00	Full ayacut achieve
133	Mayurbhanj	Saraskana	Purunapani	NSC	NSC	60.00	0.00	0.00	Handed over to SIP
134	Mayurbhanj	Saraskana	Rajabundha	4.47	4.47	200.00	200.00	200.00	Full ayacut achieve
135	Mayurbhanj	Saraskana	Rajaloka	0.2	0.2	44.00	44.00	44.00	Full ayacut achieve
136	Mayurbhanj	Saraskana	Saraskana	1	1	160.00	160.00	160.00	Full ayacut achieve
137	Mayurbhanj	Suliapada	Bhaduasole MIP(Res)	3.84	2.5	60.00	40.00	35.00	Present water level is below FRL
138	Mayurbhanj	Suliapada	Bhandarisole MIP(Res)	3.3	2	84.00	40.00	20.00	Present water level is below FRL
139	Mayurbhanj	Suliapada	Fania MIP(Res)	10.91	7	400.00	337.00	250.00	Present water level is below FRL
140	Mayurbhanj	Suliapada	Gendakhal MIP(Res)	2.7	2	142.00	94.00	94.00	Present water level is below FRL
141	Mayurbhanj	Suliapada	Gulfa MIP (D/W)	5.3	4	200.00	180.00	150.00	Less run-off due to scanty rainfall.
142	Mayurbhanj	Suliapada	Jamsole MIP(Res)	2.25	1.25	60.00	60.00	40.00	Less run-off due to scanty rainfall.
143	Mayurbhanj	Suliapada	Munduribandha MIP(Res)	6.5	5	125.00	125.00	100.00	Present water level is below FRL
144	Mayurbhanj	Suliapada	Pachakhali MIP(Res)	3.25	2.5	120.00	120.00	100.00	Present water level is below FRL
145	Mayurbhanj	Suliapada	Pandusole MIP(Res)	3.3	2.1	52.00	52.00	40.00	Present water level is below FRL
146	Mayurbhanj	Suliapada	Tulsa			40.00	0.00	0.00	Non existiting
147	Mayurbhanj	Udala	Deo (D/W)	19.65	18.2	1280.00	1150.00	1150.00	Less availability of water in river
148	Mayurbhanj	Udala	Dhadichua (D/W)	1.5	1.5	55.00	55.00	50.00	Less run-off due to scanty rainfall
149	Mayurbhanj	Udala	Jayabundha	0.6	0.6	86.00	30.00	25.00	Ayacut overlapped by Sunei Medium Irr. Project
150	Mayurbhanj	Udala	Khadikasole (Res)	1.4	1.3	50.00	40.00	40.00	Present water level is below FRL
151	Mayurbhanj	Udala	Nabaradesabundha	NCS		46.00	0.00	0.00	Over lapped by Kalo Irrigation Project
152	Mayurbhanj	Udala	Nayarangamatia (D/W)	13.9	12.8	1000.00	850.00	850.00	Less availability of water in river
153	Mayurbhanj	Udala	Nuagan (Res)	1.6	1.6	30.00	40.00	30.00	Less Rainfall
154	Mayurbhanj	Udala	Rajabundha (Res)	6.5	4.2	140.00	122.00	100.00	Present water level is below FRL
155	Mayurbhanj	Udala	Sanjo (D/W)	13.3	10.5	748.00	668.00	615.00	Less availability of water in river
						<b>Total: 26003.00</b>	<b>21408.00</b>	<b>19975.00</b>	