

IRRIGATION SUPPLIED DURING KHARIFF AS ON SEPTEMBER 2015 IN MAYURBHANJA DISTRICT

Sl No.	Name of District	Name of Block	Name of MIP	Length of canal system in Km		Ayacut in Ha.			Reason for less/ excess of ayacut irrigated/ Reason for not reaching tail end
				Design length	Actual length in which water supplied	Designed Ayacut	Actual Potential Created	Ayacut irrigated upto 30th Sept'2015	
1	2	3	4	5	6	7	8	9	10
1	Mayurbhanj	Bahalda	Rajabundha	1.00	0.60	40.00	42.04	20.00	Insufficient water in reservoir
2	Mayurbhanj	Bahalda	Sunaposi	13.00	8.00	650.00	514.00	300.00	Due to want of renovation & insufficient water
3	Mayurbhanj	Bahalda	Guhaldihi	1.70	1.50	331.70	280.00	330.00	Insufficient water in reservoir
4	Mayurbhanj	Bijatala	Ambodiha	1.00	0.80	82.00	81.32	66.00	Due to want of renovation
5	Mayurbhanj	Bijatala	Bijatala	0.80	0.70	132.00	144.74	93.00	Insufficient water in reservoir
6	Mayurbhanj	Bijatala	Madansila	2.00	1.70	100.00	166.16	70.00	Insufficient water in reservoir
7	Mayurbhanj	Bijatala	Saranda	1.50	1.00	52.00	16.63	34.00	Insufficient water in reservoir
8	Mayurbhanj	Bijatala	Ektali	0.50	0.40	100.00	81.25	70.00	Insufficient water in reservoir
9	Mayurbhanj	Bijatala	Govindapur	2.00	1.40	76.00	67.00	41.0	Due to want of renovation
10	Mayurbhanj	Bijatala	Luhasila	2.60	1.40	142.00	66.37	53.00	Due to want of renovation
11	Mayurbhanj	Bijatala	Bhaliadhupa	0.00	0.00	120.00	-	30.00	NCS
12	Mayurbhanj	Jamda	Anlabeda	1.50	1.20	40.00	42.55	31.00	Insufficient water in reservoir
13	Mayurbhanj	Jamda	Dhalpur	1.50	1.30	90.00	97.23	70.00	Insufficient water in reservoir
14	Mayurbhanj	Jamda	Maranda	1.20	1.00	60.0	61.86	52.00	Insufficient water in reservoir
15	Mayurbhanj	Jamda	Jatapani	1.90	1.50	60.00	64.09	48.00	Insufficient water in reservoir
16	Mayurbhanj	Jamda	Sunamara	5.40	3.80	107.00	73.67	76.00	Insufficient water in reservoir
17	Mayurbhanj	Jamda	Tendrasakjodi	4.75	3.20	348.00	269.00	190.00	Due to want of Renovation
18	Mayurbhanj	Jamda	Manbir MIP	0.55	0.30	40.00	-	25.00	On going
19	Mayurbhanj	Jamda	JoJosahi MIP	3.025	2.00	80.00	-	43.00	On going
20	Mayurbhanj	Jashipur	Dhatikia	2.60	2.20	100.00	146.04	75.00	Insufficient water in reservoir
21	Mayurbhanj	Jashipur	Kudarbisida	1.50	1.00	48.00	48.63	25.00	Insufficient water in reservoir
22	Mayurbhanj	Jashipur	Kumudabadi	5.37	4.10	320.00	444.00	230.00	Renovation work on progress
23	Mayurbhanj	Jashipur	Mahardapalsa	0.20	0.20	54.00	54.60	45.00	Full Supply
24	Mayurbhanj	Jashipur	Sananai	1.10	1.00	42.00	40.52	40.00	Full Supply
25	Mayurbhanj	Jashipur	Tangabilla	1.50	0.80	40.00	23.56	20.00	Insufficient water in reservoir
26	Mayurbhanj	Jashipur	Chhamundia	8.30	6.00	280.00	242.12	160.00	Due to want of renovation
27	Mayurbhanj	Jashipur	Sansialinai	6.00	5.00	400.00	234.01	222.00	Due to want of renovation
28	Mayurbhanj	Jashipur	Begunia	1.00	1.00	43.00	16.47	40.00	Full Supply
29	Mayurbhanj	Jashipur	Manada	0.23	0.23	52.00	-	12.00	On going
30	Mayurbhanj	Jashipur	Dighiposi MIP	0.00	0.00	50.00	-	-	On going
31	Mayurbhanj	Jashipur	Chakidi MIP	0.00	0.00	120.00	-	-	On going
32	Mayurbhanj	Karanjia	Bisipur	3.10	1.60	47.00	48.00	34.00	Due to want of Renovation and insufficient water in reservoir
33	Mayurbhanj	Karanjia	Chitraposi	1.00	0.80	80.00	80.59	60.00	Due to want of renovation
34	Mayurbhanj	Karanjia	Hatibari	2.00	1.80	180.00	187.68	130.00	Due to want of renovation
35	Mayurbhanj	Karanjia	Kadadiha	0.71	0.71	72.00	73.99	40.00	Due to want of renovation
36	Mayurbhanj	Karanjia	Kendumundi	1.00	0.80	40.00	46.27	36.00	Insufficient water in reservoir
37	Mayurbhanj	Karanjia	Neduapal	3.00	2.50	115.00	115.00	80.00	Insufficient water in the reservoir.
38	Mayurbhanj	Karanjia	Panaspal	1.50	1.30	124.00	124.61	80.00	Insufficient water in reservoir
39	Mayurbhanj	Karanjia	Pingu	1.10	1.10	120.00	128.62	120.00	Insufficient water in the reservoir.
40	Mayurbhanj	Karanjia	Rajabandha	2.60	1.60	160.00	191.98	100.00	Insufficient water in the reservoir.
41	Mayurbhanj	Karanjia	Ramchandrapur	1.30	1.10	50.00	50.40	41.00	Insufficient water in the reservoir.
42	Mayurbhanj	Karanjia	Tato	0.00	0.00	40.00	50.35	10.00	Due to want of renovation
43	Mayurbhanj	Karanjia	Sarangagarh MIP	3.20	2.80	40.00	-	37.00	Insufficient water in the reservoir and want of renovation
44	Mayurbhanj	Karanjia	Viol	3.00	2.30	80.00	62.20	58.00	Due to want of renovation
45	Mayurbhanj	Karanjia	Karadiha	0.40	0.40	131.00	107.47	85.00	Due to want of renovation
46	Mayurbhanj	Karanjia	Salarpada	1.48	1.20	65.00	29.56	55.00	Insufficient water in the reservoir.
47	Mayurbhanj	Kusumi	Jhipabundha	3.20	2.80	280.00	280.00	240.00	Insufficient water in reservoir and wat of renovation
48	Mayurbhanj	Kusumi	Dalkijorda	11.20	8.00	320.00	304.70	230.00	Insufficient water in reservoir and wat of renovation

49	Mayurbhanj	Kusumi	Aharbuntha	6.74	6.74	200.00	162.86	200	Full Supply
50	Mayurbhanj	Rairangpur	Kukudimundi	2.00	1.50	40.00	53.04	35.00	Due to want of Renovation
51	Mayurbhanj	Rairangpur	Sudarsanapur	3.10	2.00	40.00	45.81	30.00	Insufficient water in reservoir
52	Mayurbhanj	Rairangpur	Tamalbandha	1.69	1.00	42.00	42.22	30.00	Insufficient water in reservoir
53	Mayurbhanj	Rairangpur	Patepani	1.54	1.20	136.00	58.84	70.00	Insufficient water in reservoir
54	Mayurbhanj	Rairangpur	Guhaladangri	1.00	0.70	60.00	50.10	37.00	Insufficient water in reservoir
55	Mayurbhanj	Rairangpur	Samadafa	2.00	1.20	76.00	68.78	37.00	Due to want of renovation
56	Mayurbhanj	Rairangpur	Udayapur	0.80	0.60	63.00	49.10	40.00	Due to want of renovation
57	Mayurbhanj	Rairangpur	Badra	0	0	40.00		18.00	Due to want of renovation
58	Mayurbhanj	Rairangpur	Jhulan	2.40	1.60	50.00	41.30	41.00	Due to want of renovation and insufficient water in reservoir
59	Mayurbhanj	Rairangpur	Vesarkocha	6.70	3.6	220.00	43.15	98.00	Due to want of renovation and insufficient water in reservoir
60	Mayurbhanj	Raruan	Chutianalla	4.30	3.30	200.00	199.78	150.00	Due to want of renovation
61	Mayurbhanj	Raruan	Kantasimla	1.70	0.80	130.00	138.38	80.00	Due to want of renovation
62	Mayurbhanj	Raruan	Nanduburu	2.00	0.00	60.00	61.38	20.00	Due to want of renovation
63	Mayurbhanj	Raruan	Righa	1.50	0.00	48.00	48.38	10.00	Insufficient water in reservoir
64	Mayurbhanj	Raruan	Riteisahi	0.80	0.20	60.00	61.36	10.00	Insufficient water in reservoir
65	Mayurbhanj	Raruan	Solagada	1.00	0.00	88.00	88.65	20.00	Insufficient water in reservoir
66	Mayurbhanj	Raruan	Jharbeda	5.61	3.20	174.00	174.00	100.00	Due to want of renovation
67	Mayurbhanj	Raruan	Angarpada	0.20	0.00	40.00	31.95	-	Renovation work on progress
68	Mayurbhanj	Raruan	Gadapalasa	4.30	0.00	285.00	284.83	150.00	Due to want of renovation
69	Mayurbhanj	Sukruli	Badateranti	2.20	0.00	95.00	95.53	5.00	Due to want of renovation
70	Mayurbhanj	Sukruli	Baria	0.92	0.50	140.00	70.29	50.00	Insufficient water in reservoir
71	Mayurbhanj	Sukruli	Haladia	5.67	3.20	160.00	108.76	80.00	Due to want of renovation
72	Mayurbhanj	Sukruli	Jhadghosada	3.60	2.80	60.00	51.50	20.00	Insufficient water in reservoir
73	Mayurbhanj	Thakurmunda	Champajhar	5.90	3.20	293.00	301.53	290.00	Full Supply
74	Mayurbhanj	Thakurmunda	Digdhar	2.00	1.70	78.00	79.26	75.00	Full Supply
75	Mayurbhanj	Thakurmunda	Gobarjoda	3.00	2.50	40.00	53.30	35.00	Full Supply
76	Mayurbhanj	Thakurmunda	Akhapalam	3.00	2.70	54.00	34.96	46.00	Full Supply
77	Mayurbhanj	Thakurmunda	Chakulia	2.11	1.00	60.00	42.78	35.00	Due to want of renovation and insufficient water in reservoir
78	Mayurbhanj	Thakurmunda	Vejidhia	2.50	2.00	80.00	61.41	75.00	Full Supply
79	Mayurbhanj	Thakurmunda	Joram	0.00	0.00	200.00	-	-	On going
80	Mayurbhanj	Tiring	Narayanpur	3.30	2.70	80.00	74.61	61.00	Insufficient water in reservoir
81	Mayurbhanj	Tiring	Chengua	0.40	0.35	40.00	20.00	38.00	Insufficient water in reservoir
82	Mayurbhanj	Tiring	Kochagobra	3.50	2.80	64.00	47.00	41.00	Insufficient water in reservoir
83	Mayurbhanj	Tiring	Nuagaon	3.50	2.50	60.00	48.00	48.00	Insufficient water in reservoir
84	Mayurbhanj	Tiring	Pokharia	7.07	5.70	300.00	240.95	150.00	Due to want of renovation
			Total:	211.57	145.43	9,999.70	8,233.07	6,172.00	